

Port of London Authority Chart Correction Advice Date: 22nd April 2016


CCA No: 2016/13



**Chart: Upper Pool** 

PLA Chart No. 318 HO Ref No. 113-318-266 Previous Chart Correction: 2015/28

The accompanying block correction shows that PLA Mill Stairs Buoy with associated ground tackle and screws, located off Chambers Wharf, have been removed from the river.



For further information see the PLA hydrographic service website:

http://www.pla.co.uk/Safety/PLA-Hydrographic-Service-Published-Surveys