

Port of London Authority Chart Correction Advice Date: 19th April, 2018


CCA No: 2018/11



Chart: Nine Elms Reach

PLA Chart No. 315 HO Ref No. 113-315-050 Previous Chart Correction: 2018/7

The accompanying block correction shows: New Jetty & conveyor at Kirtling Street, Nine Elms works



For further information see the PLA hydrographic service website:

http://www.pla.co.uk/Safety/PLA-Hydrographic-Service-Published-Surveys