

Port of London Authority Chart Correction Advice Date:13th December, 2019



CCA No: 2019/40

Chart: Limehouse Reach to Greenwich Reach

PLA Chart No. 320 HO Ref No. 113-320-059 Previous Chart Correction: 2019/27

The accompanying block correction shows: Removal of the Navigation light, Convoys Wharf (Lower)



For further information see the PLA hydrographic service website:

http://www.pla.co.uk/Safety/PLA-Hydrographic-Service-Published-Surveys